



**PROJECT TITLE:** Inpit (filtered) tailings deposition - stockpile stability analysis.

**PARTNERING CLIENT:** Broken Hill Mines

**LOCATION:** New South Wales (NSW)

### Project Details:

Geotailnics conducted stability assessments for deposition of inpit filtered tailings stockpile. Stability analysis included understanding of critical state parameters for filtered tailings post-conveyance from the dewatering plant and deposition before spreading and compaction processes.

